


Ν

breached levee system is not repaired (either to prior specificatio or temporary/permanent but not to prior specifications) by the latter of the sales closing date or earliest planting date.



Map Created by: RMA, Topeka Regional Office, Topeka, KS Map Creation Date: 9/1/2021 Map Projection: NAD 1983 UTM Zone 15N Projection: Transverse MercatorNorth American 1983

The information displayed in this map is intended to serve as an aid in displaying data provided or stored by the Risk Management Agency. It does not modify, replace, or supersede any USDA published policy provisions or procedures.